

Inspection Photos

05/15/2018

Operator: PRONGHORN OPERATING LLC - 10422

Location ID: 387156

Inspection Doc. Number: 682503359

Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PRONGHORN OPERATING LLC - 10422
Location ID: 387156



Photo 1: Photo taken from the south of the location, facing south. Photo shows access road. Operator has submitted a 502.b variance request to no reclaim access road.



Photo 2: Photo taken from the access road entrance, facing north. Photo shows cattle guard and access road.

Inspection Photos
Operator: PRONGHORN OPERATING LLC - 10422
Location ID: 387156



Photo 3: Photo taken from the south end of the location, facing northwest. Photo shows overview of the location.



Photo 4: Photo taken from the south end of the location, facing northeast. Photo shows overview of the location.

Inspection Photos
Operator: PRONGHORN OPERATING LLC - 10422
Location ID: 387156



Photo 5: Photo taken from the center of the location, facing north. Photo shows vegetation on the location is predominantly undesirable weedy plant species, or is bare and exposed soil. Unable to find desirable perennial vegetative establishment or germination evident on the location.



Photo 6: Photo taken from the center of the location, facing east. Photo shows vegetation on the location is predominantly undesirable weedy plant species, or is bare and exposed soil. Unable to find desirable perennial vegetative establishment or germination evident on the location.

Inspection Photos
Operator: PRONGHORN OPERATING LLC - 10422
Location ID: 387156



Photo 7: Photo taken from the center of the location, facing south. Photo shows vegetation on the location is predominantly undesirable weedy plant species, or is bare and exposed soil. Unable to find desirable perennial vegetative establishment or germination evident on the location.



Photo 8: Photo taken from the center of the location, facing west. Photo shows vegetation on the location is predominantly undesirable weedy plant species, or is bare and exposed soil. Unable to find desirable perennial vegetative establishment or germination evident on the location.

Inspection Photos
Operator: PRONGHORN OPERATING LLC - 10422
Location ID: 387156



Photo 9: Photo taken from the north end of the location. Photo shows pipe remaining.



Photo 10: Photo taken from the north end of the location. Photo shows debris remaining.