

UTE 34-10 #101R

Corrective Actions Taken on the UTE 34-10 #101R INC.

EMERGENCY NUMBER (505) 324-5170



Hilcorp Energy Company

**UTE 34-10 #101R
LATITUDE 37° .157539
LONGITUDE 107° .968853
SE/4 SE/4 SEC 30 T34N R10W
960' FSL 1100' FEL**

**DWR
71025-F**

**LA PLATA COUNTY, COLORADO
FRUITLAND COAL**



Corrective action taken for Photo 6 & 7 from inspection report. Stormwater management controls have been established to stabilize erosion in the Northeast portion of project area.





Corrective action taken for Photo 4 & 5 from inspection report. All Musk Thistle debris have been removed from the project area and properly disposed of.



