

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401495814

Date Received:

12/27/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685

Name of Operator: KINDER MORGAN CO2 CO LP

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Swift, Barry

970-882-5545

barry_swift@kindermorgan.com

Millican, Chris

chris_millican@kindermorgan.com

Hannigan, Michael

(970) 882-5532

michael_hannigan@kindermorgan.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602294

Inspection Date: 11/16/2017

FIR Submit Date: 12/14/2017

FIR Status: _____

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP

Company Number: 46685

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 313616

Location Name: GOODMAN POINT (GP#15)- N36N17W Number: 18NWNE County: MONTEZUMA

Qtrqtr: NWNE Sec: 18 Twp: 36N Range: 17W Meridian: N

Latitude: 37.383815 Longitude: -108.761536

FACILITY - API Number: 05-083- -00 Facility ID: 295002

Facility Name: GOODMAN POINT Number: 15

Qtrqtr: NWNE Sec: 18 Twp: 36N Range: 17W Meridian: N

Latitude: 37.383815 Longitude: -108.761536

CORRECTIVE ACTIONS:

1 ☒ CA# 113397

Corrective Action: Provide COGCC inspectors access to locked gates to facilitate reasonable access. Gate codes, keys, or the ability to install a state-owned lock on a lock chain is needed. If operator has safety concerns for access they need to notify COGCC inspectors of the concern and extent of risk.

Date: 12/29/2017

Response: CA COMPLETED

Date of Completion: 12/21/2017

Operator Comment: Per phone conversation with Margaret Ash on 12/20/2017, Kinder Morgan CO2 (KM) has agreed to allow COGCC inspectors the ability to install state-owned locks on the locations with restricted access identified on the attached spreadsheet and facilities maps. Several of the facilities identified on the attached spreadsheet and facilities maps will require a Kinder Morgan escort.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Lopez

Signed: _____

Title: EHS Specialist

Date: 12/27/2017 8:38:12 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401495814	FIR RESOLUTION SUBMITTED
401495829	Well locations with Restricted Access
401495830	Facilities Map Cow Canyon
401495831	Facilities Map Doe Canyon
401495832	Facilities Map Hovenweep
401495833	Facilities Map South Gathering
401495835	Facilities Map Yellow Jacket

Total Attach: 7 Files