

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2018

Submitted Date:

05/16/2018

Document Number:

682403590**FIELD INSPECTION FORM**
 Loc ID 305734 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">ALL INSPECTIONS</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281476	WELL	TA	07/05/2017	OW	123-23409	JEFFERS 21-35	RI

**General Comment:**

This is an Interim Reclamation and Stormwater Inspection at the battery location associated with JEFFERS #21-35 well. Any corrective actions from previous inspections that have not been addressed are still applicable.



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Appears stormwater runoff from the battery location is causing rill erosion off location. There were no observed BMPs being implemented along the battery location to minimize erosion- Photos 1-3. A cattle guard along the main access road is in need of maintenance- Photo 4. Refer to the attached inspection photos for more detail. See COGCC comments for more information.

Corrective Action: Install or repair required BMPs per Rule 1002.f. This is a short corrective action date because monsoon weather conditions have already started to occur.

Date: 05/23/2018

Pits: ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
A similar inspection will be sent to the other Operator that also uses the cattle guard BMP on the main access road. Both Operator's will need to coordinate to perform the required maintenance for that BMP- Photo 4.	binschusc	05/16/2018
Operator shall employ BMPs, as necessary to comply with Rule 1002.f., at all oil and gas locations, including, but not limited to, well pads, soil stockpiles, access roads, tank batteries, compressor stations, and pipeline rights of way. BMPs shall be selected based on site-specific conditions, such as slope, vegetation cover, and proximity to water bodies, and may include maintaining in-place some or all of the BMPs installed during the construction phase of the facility. Where applicable based on site-specific conditions, Operator shall implement BMPs in accordance with good engineering practices.	binschusc	05/16/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401643010	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4465243">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4465243</a>
682403591	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4465240">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4465240</a>