

MCCULLOCH # 1

Corrective Actions Taken on the MCCULLOCH #1 for COGCC INC.

McCulloch #1

05/25/18



Stabilized berms and cleaned sediment out of the northern Storm Water diversion channel. Storm Water management run-on controls have been maintained to further stabilize and control erosion in the Northern portion of the project area. Crimped and seeded the cut-slope downstream of wattles.



Corrective action taken for Photo 4 from inspection report



Corrective action taken for Photo 4 from inspection report

Storm Water management controls have been established to stabilize erosion in the Northeastern portion of the project area.



Corrective action taken for Photo 5 from inspection report



Corrective action taken for Photo 5 from inspection report

Stabilized berm and cleaned sediment out of the Western Storm Water diversion channel. Crimped and seeded cut-slope.



Storm Water management controls have been maintained to further stabilize and control erosion along the Southern edge of the working surface.



Corrective action taken for Photo 3 from inspection report

Reclaimed well pad surface with the exception of the tear drop driving surface, crimped seeded the area.





Preformed maintenance to further stabilize silt-trap and culvert.

