

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/24/2018

Submitted Date:

05/29/2018

Document Number:

679700925**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
ALLISON, RICK 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Jeremy Ferrin		dnr_cogccenforcement@state.co.us	
Sheila Singer		ssinger@hpres.com	
Matt Barber		mbarber@hpres.com	
Axelsson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448950	LAND APPLICATION SITE				-	SANDY HILL 5-61-29	EI

General Comment:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Land Application	Adequate		
Comment	COGCC followup inspection to Sandy Hill Land Application site. Cuttings and drilling fluid has been incorporated. Recent rain has generated overland flow of water and drilling mud with site soil. Berms on western edge of site have been breached, but stormwater and sediment was contained in the perimeter ditch. No additional offsite impacts were observed.			
Corrective Action	Inspection and maintain stormwater controls to prevent further degradation of controls and to prevent offsite impacts results from stormwater flow. Perform corrective actions by deadline or prior to next storm event.			Date: 06/05/2018

Spill/Remediation:

Comment:	See photos of spill areas. Grass is growing through both spill areas.			
Corrective Action:	Submit status update via email or via Form 27 Supplemental for cleanup of Winick property.			Date: 06/29/2018

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700926	Sandy Hill Site Photos 05-24-2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4476403