

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401643267  
Date Received:  
05/17/2018

## FIR RESOLUTION FORM

### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

### Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		sabre.beebe@bp.com
Inspections, All		SanJuanCOGCC@bp.com
St John, William (Cal)		cal.stjohn@state.co.us

### COGCC INSPECTION SUMMARY:

FIR Document Number: 685200425  
Inspection Date: 03/26/2018 FIR Submit Date: 03/27/2018 FIR Status:

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 326067

Location Name: MW JOHNSON G A-M34N8W Number: 16NWNW County: LA PLATA  
Qtrqr: NWN Sec: 16 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.195509 Longitude: -107.727750

### FACILITY - API Number: 05-067- -00 Facility ID: 215812

Facility Name: MW JOHNSON A Number: 1  
Qtrqr: NWN Sec: 16 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.195509 Longitude: -107.727750

### CORRECTIVE ACTIONS:

1 ☒ CA# 115261

Corrective Action: use or remove parts and equipment per Rule 603.f Date: 04/27/2018

Response: CA COMPLETED Date of Completion: 05/25/2018

All operator debris removed from location and properly disposed of. See attached photos

Operator  
Comment:

COGCC Decision: Approved via an AMI

COGCC  
Representative:

2 ☒ CA# 115262

Corrective Action: Stop release as soon as possible and no later than corrective action date, take necessary steps in engine repair or muffle re-configuration to prevent recurrence per Rules 906 & 907 (see stormwater section for CA regarding removal of impacted material)

Date: 04/06/2018

Response: CA COMPLETED

Date of Completion: 04/06/2018

Operator  
Comment:

Containment box installed on muffler to prevent future staining of soils from exhaust.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 115263

Corrective Action: Clean up (do not cover) impacted material on east side of pumping unit (see photos) per applicable parts of Rules 906, 907 and 1002.f

Date: 04/06/2018

Response: CA COMPLETED

Date of Completion: 04/06/2018

Operator  
Comment:

All stained soils have been excavated from location and disposed of in the soil box at the BP Durango Operations Center for batch remediation at IEI in Farmington NM. Clean soils have been placed back into excavation areas to address this CA. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All Corrective actions have been addressed on this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 5/17/2018 7:49:15 AM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401643267	FIR RESOLUTION SUBMITTED
401643294	CA closure photos

Total Attach: 2 Files