

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401668421

Date Received:

06/08/2018

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Sessions, Tamra

tsessions@logosresourcesllc.com

Rowley, Darren

drowley@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602725

Inspection Date: 05/17/2018

FIR Submit Date: 06/04/2018

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 325168

Location Name: IGNACIO 33-8-N33N8W Number: 1E2SW County: LA PLATA

Qtrqr: E2SW Sec: 1 Twp: 33N Range: 8W Meridian: N

Latitude: 37.129360 Longitude: -107.671140

FACILITY - API Number: 05-067- -00 Facility ID: 214188

Facility Name: IGNACIO 33-8 Number: 2

Qtrqr: E2SW Sec: 1 Twp: 33N Range: 8W Meridian: N

Latitude: 37.129360 Longitude: -107.671140

CORRECTIVE ACTIONS:

1 CA# 116657

Corrective Action: Remove debris,

Date: 07/06/2018

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment belongs to the surface owner

Operator
Comment:

The Ignacio 33-8 #2 was drilled in 1955. Historically, LOGOS and its predecessors have designated surface use area as the larger of the rig anchor pattern or the total equipment footprint. The "wood and metal debris within the eastern portion of the project area" noted in inspection #401661670 is located outside of the surface use area, was not placed by LOGOS personnel and was not part of LOGOS's equipment. Based upon our

investigation, the debris is property of the surface owner. Accordingly, LOGOS does not have authority to move the debris on behalf of the surface owner.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larissa Farrell

Signed:

Title: Regulatory Technician

Date: 6/8/2018 3:22:08 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files