

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401603005
Date Received:
04/10/2018

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685304334
Inspection Date: 02/09/2018 FIR Submit Date: 02/13/2018 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333694

Location Name: MAESTAS GAS UNIT A- N33N9W Number: 23SWNE County: LA PLATA
Qtrqr: SWNE Sec: 23 Twp: 33N Range: 9W Meridian: N
Latitude: 37.090196 Longitude: -107.791438

FACILITY - API Number: 05-067- -00 Facility ID: 276849

Facility Name: MAESTAS A Number: 2
Qtrqr: SWNE Sec: 23 Twp: 33N Range: 9W Meridian: N
Latitude: 37.090196 Longitude: -107.791438

CORRECTIVE ACTIONS:

1 ☒ CA# 114409

Corrective Action: Clean-up and remediate impacted soil to comply with Rule 906.a. Date: 03/16/2018

Response: CA COMPLETED Date of Completion: 03/12/2018

Operator Comment: Stained soils have been physically removed from location and deposited into the IEI waste box for batch remediation at the BP Office. Hole where soils have been removed has been back filled with clean soils. See attached photos.

COGCC Decision: Approved

COGCC Representative: Approved based on operator submitted photo documentation.

2 ☒ CA# 114410

Corrective Action: Install signage/labels in conspicuous place to comply with Rule 210.

Date: 04/15/2018

Response: CA COMPLETED

Date of Completion: 03/12/2018

Operator Comment: Tank sign has been installed on the fencing around the tank see attached photos

COGCC Decision: Approved

COGCC Representative: Approved based on operator submitted photo documentation.

3 ☒ CA# 114411

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f.

Date: 04/11/2018

Response: CA COMPLETED

Date of Completion: 03/12/2018

Operator Comment: Rock run down has been installed in erosion channel for infiltration and filtration of storm water flowing off the well pad. See attached photos. Location has been graded to direct storm water flow to the rock run down to prevent addition channels from beginning.

COGCC Decision: Approved

COGCC Representative: Approved based on operator submitted photo documentation.

OPERATOR COMMENT AND SUBMITTAL

Comment: All Corrective actions have been completed on this location and new sign is on order for the location and will be installed upon completion to address the inspector comment regarding sign peeling and needing replacement.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 4/10/2018 5:39:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401603005	FIR RESOLUTION SUBMITTED
401603007	CA Completion photos

Total Attach: 2 Files