

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401564801

Date Received:

03/06/2018

## FIR RESOLUTION FORM

### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

pshorty@hilcorp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 680602462

Inspection Date: 02/01/2018

FIR Submit Date: 02/01/2018

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

### LOCATION - Location ID: 333489

Location Name: SOUTHERN UTE 33-9- N33N9W Number: 17NWSE County: LA PLATA

Qtrqtr: NWSE Sec: 17 Twp: 33N Range: 9W Meridian: N

Latitude: 37.100280 Longitude: -107.844960

### FACILITY - API Number: 05-067- -00 Facility ID: 89097

Facility Name: SOUTHERN UTE 33-9 Number: 17-2

Qtrqtr: NWSE Sec: 17 Twp: 33N Range: 9W Meridian: N

Latitude: 37.100280 Longitude: -107.844960

### CORRECTIVE ACTIONS:

1 ☒ CA# 114263

Corrective Action: Remove and properly dispose of Russian thistle debris.

Date: 03/23/2018

Response: CA COMPLETED

Date of Completion: 03/05/2018

Operator  
Comment:

The Russian thistle debris have been removed. See attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 114264

Corrective Action: Mark or remove rig anchors.

Date: 03/23/2018

Response: CA COMPLETED

Date of Completion: 03/05/2018

Operator  
Comment: All rig ancors have been properly marked. See attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 114265

Corrective Action: Stabilize erosion within the project area. Areas of bare soil such as the northern cut-slopes and southern fill slopes need to be stabilized with erosion control products and revegetated. Erosional channels need to be stabilized. Stormwater run-on and sediment need to be managed and maintained. Corrective action date is extended to April 27, 2018 to accomodate for potential winter conditions.

Date: 04/27/2018

Response: CA COMPLETED

Date of Completion: 03/06/2018

Operator  
Comment: Stormwater management erosion control channels have been established adn stabilized in order to prevent future erosion off location. Location has been reclaimed and seeded to stabilize erosion. See attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions are completed for Doc # 680602462. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: Operations Reg Technician

Date: 3/6/2018 1:21:36 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401564801	FIR RESOLUTION SUBMITTED
401564818	Southern Ute 33-9 17-2 Corrective Action Photos

Total Attach: 2 Files