

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401686260  
Date Received:  
06/27/2018

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC  
Address: 410 17TH STREET SUITE #1400  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

| Contact Name       | Phone             | Email                        |
|--------------------|-------------------|------------------------------|
| <u>Luke Kelly</u>  | <u>7203158934</u> | <u>Lkelly@Bonanzacrk.com</u> |
| <u>Brian Dodek</u> | <u>7204406100</u> | <u>BDodek@Bonanzacrk.com</u> |

### COGCC INSPECTION SUMMARY:

FIR Document Number: 682403682  
Inspection Date: 06/11/2018 FIR Submit Date: 06/13/2018 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Company Number: 8960  
Address: 410 17TH STREET SUITE #1400  
City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 449728

Location Name: State Antelope Number: 41-11 Pad County: \_\_\_\_\_  
Qtrqtr: NENE Sec: 11 Twp: 5N Range: 62W Meridian: 6  
Latitude: 40.421863 Longitude: -104.283502

### FACILITY - API Number: 05-123-00 Facility ID: 449728

Facility Name: State Antelope Number: 41-11 Pad  
Qtrqtr: NENE Sec: 11 Twp: 5N Range: 62W Meridian: 6  
Latitude: 40.421863 Longitude: -104.283502

### CORRECTIVE ACTIONS:

1 ☒ CA# 116787

Corrective Action: Operator shall stabilize the topsoil stockpile to ensure compliance under Rule 1002.c. Date: 06/27/2018

Response: CA COMPLETED Date of Completion: 06/27/2018

Operator Comment: The topsoil stockpile was stabilized with hydromulch and tackifier to ensure compliance under Rule 1002.c. Photos of the work being completed are included as attachments.

COGCC Decision: Approved via an AMI

COGCC Representative: Appears the Operator has stabilized the topsoil stockpile per the corrective action. Operator shall monitor BMP, as hydromulch/tackifier is only a temporary stabilization BMP and may require additional maintenance.

Operator shall ensure compliance with other sections of Rule 1002c, like, preventing weed establishment and to maintain soil microbial activity.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Kelly

Signed: \_\_\_\_\_

Title: Environmental Specialist

Date: 6/27/2018 2:02:12 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <b><u>Document Number</u></b> | <b><u>Description</u></b> |
|-------------------------------|---------------------------|
| 401686260                     | FIR RESOLUTION SUBMITTED  |
| 401687485                     | Stockpile Photo 2         |
| 401687486                     | Stockpile Photo 1         |
| 401687488                     | Stockpile Photo 3         |

Total Attach: 4 Files