

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2018

Submitted Date:

07/13/2018

Document Number:

689801355**FIELD INSPECTION FORM**Loc ID 314522 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 82440Name of Operator: STEHLE OIL COMPANYAddress: P O BOX 1577City: CRAIG State: CO Zip: 81626**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
		dnr_cogccenforcement@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Stehle, Cary	(970) 824-6909	carystehle@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228908	WELL	SI	09/08/2014	OW	103-05906	PINNACLE UNIT 12-30	WK

General Comment:FIU MIT witness.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
PW/CO				
Comment:	Stained soil on tank berm.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 08/13/2018

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 228908 Type: WELL API Number: 103-05906 Status: SI Insp. Status: WK**Workover**Comment: Inspector on location to witness MIT. Operator was unable to maintain pressure. Test failed.Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.Date: 07/27/2018**COGCC Comments**

Comment	User	Date
Inspector on location to witness MIT. A follow up inspection to previous inspections as well as this MIT witness, will be performed after workover removal.	waldrone	07/13/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689801357	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4523438