

HALLIBURTON

iCem[®] Service

SRC Energy

Date: Wednesday, May 16, 2018

Harvesters State 4N-16A-M Production

Job Date: Sunday, May 06, 2018

Sincerely,
Tyler Hill

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0	Cementing Job Summary	4
1.1	Executive Summary	4
2.0	Real-Time Job Summary	7
2.1	Job Event Log	7
3.0	Attachments.....	10
3.1	Harvesters State 4N-16A-M Production.png.....	10

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Harvesters State** cement **Production** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 26 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Ft. Lupton

The Road to Excellence Starts with Safety

Sold To #: 359915	Ship To #: 3858713	Quote #:	Sales Order #: 0904832251
Customer: SRC ENERGY INC-EBUS		Customer Rep: Steve Wilson	
Well Name: HARVESTERS STATE		Well #: 4N-16A-M	API/UWI #: 05-123-46362-00
Field: WATTENBERG	City (SAP): LUCERNE	County/Parish: WELD	State: COLORADO
Legal Description: SW NE-15-6N-66W-1673FNL-2333FEL			
Contractor: Precision		Rig/Platform Name/Num: Precision 462	
Job BOM: 7523 7523			
Well Type: HORIZONTAL OIL			
Sales Person: HALAMERICA\HB41307		Srvc Supervisor: Luke Kosakewich	

Job

Formation Name			
Formation Depth (MD)	Top		Bottom
Form Type	BHST		
Job depth MD	14855ft	Job Depth TVD	6,957ft
Water Depth		Wk Ht Above Floor	
Perforation Depth (MD)	From		To

Well Data

Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing		9.625	8.921	36	LTC	J-55	0	1825	0	1825
Casing	0	5.5	4.778	20	BTC	P-110	0	14844	0	6957
Open Hole Section			8.5				1825	14855	1825	6957

Tools and Accessories

Type	Size in	Qty	Make	Depth ft	Type	Size in	Qty	Make
Guide Shoe					Top Plug	5.5	1	Weatherford
Float Shoe	5.5	1	Weatherford	14844	Bottom Plug	5.5	1	Weatherford
Float Collar	5.5	1	Weatherford	14794	SSR plug set			
Wet Shoe Sub	5.5	1	Weatherford	14735	Plug Container	5.5	1	HES
Stage Tool	5.5				Centralizers	5.5	222	

Fluid Data

Stage/Plug #: 1										
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
1	Tuned Spacer III	Tuned Spacer III	40	bbl	11.5	3.8		5		
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	

2	ElastiCem LEAD	ELASTICEM (TM) SYSTEM	1016	sack	13.2	1.57		8	7.54	
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
3	NeoCem	NeoCem TM	987	sack	13.2	2.04		8	9.77	
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
4	MMCR Displacement	MMCR Displacement	20	bbl	8.34			8		
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
5	Water	Water and Biocide	237	bbl	8.33			9		
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
6	MMCR Displacement	MMCR Displacement	70	bbl	8.34			5		
Cement Left In Pipe		Amount	49 ft		Reason			Shoe Joint		
<p>Comment There were full returns throughout the job. Halliburton bumped the plug 500 psi. over 2,900 psi. at 4 bpm and held for 5 minutes. Finale pressure was 3,400 psi. Got 40 bbls. of spacer and 26 bbls. of cement to surface. Pressured up to 5,100 psi. to shift the sleeve. Pumped 6 bbls. of fresh water for a wet shoe. Bled off pressure to check floats and floats held. Got 2.5 bbls. of fluid back to the truck. Estimated TOT is 6,114'.</p>										

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	DS Pump Press <i>(psi)</i>	Comb Pump Rate <i>(bbl/min)</i>	DH Density <i>(ppg)</i>	Comments
Event	1	Call Out	Call Out	5/5/2018	22:00:00	USER				Crew was called out at 22:00 for an on location time of 03:00.
Event	2	Depart Yard Safety Meeting	Depart Yard Safety Meeting	5/6/2018	01:00:00	USER				Crew held a pre journey safety meeting and JSA.
Event	3	Depart Shop for Location	Depart Shop for Location	5/6/2018	01:10:00	USER				Started journey management with dispatch and left location.
Event	4	Arrive at Location from Service Center	Arrive at Location from Service Center	5/6/2018	02:00:00	USER				Crew performed a site assessment, safety meeting and hazard hunt on location. Checked in with the customer and discussed the job procedures, rig up and well bore schematics to calculate the job. The rig was running casing.
Event	5	Other	Other	5/6/2018	02:15:00	USER				
Event	6	Pre-Rig Up Safety Meeting	Pre-Rig Up Safety Meeting	5/6/2018	02:20:00	USER				The crew held a pre rig up safety meeting and JSA.
Event	7	Rig-Up Equipment	Rig-Up Equipment	5/6/2018	02:25:00	USER				The crew rigged up all lines, hoses and equipment for the job.
Event	8	Safety Meeting	Safety Meeting	5/6/2018	05:30:00	USER	12.00	0.00	0.00	All personnel on location held a pre cement job safety meeting and JSA.
Event	9	Start Job	Start Job	5/6/2018	06:22:02	COM5	13.00	0.00	8.09	Pumped 3 bbls. of fresh water at 3 bpm. to fill lines and establish circulation.

Event	10	Test Lines	Test Lines	5/6/2018	06:26:34	COM5	39.00	0.00	8.10	Pressure tested lines to 6,000 psi. with a 500 psi. electronic kick out test.
Event	11	Pump Spacer 1	Pump Spacer 1	5/6/2018	06:33:50	COM5	20.00	0.00	8.08	Pumped 40 bbls. of Tuned Spacer III with surfactants mixed at 11.5 ppg., Yield: 3.8 ft3/sks, 23.8 gal/sks. Density was verified by pressurized scales.
Event	12	Drop Bottom Plug	Drop Bottom Plug	5/6/2018	06:41:15	COM5	403.00	4.60	12.07	Dropped the bottom plug which was witnessed by the customer.
Event	13	Pump Lead Cement	Pump Lead Cement	5/6/2018	06:42:12	COM5	448.00	4.60	13.13	Pumped 284 bbls. (1,016 sks.) of Elasticem mixed at 13.2 ppg., Yield: 1.57 ft3/sks, 7.54 gal/sks. Density was verified by pressurized scales.
Event	14	Pump Tail Cement	Pump Tail Cement	5/6/2018	07:19:08	COM5	687.00	8.00	13.34	Pumped 359 bbls. (987 sks.) of Neocem mixed at 13.2 ppg. Yield: 2.04 ft3/sks, 9.77 gal/sks. Density was verified by pressurized scales.
Event	15	Shutdown	Shutdown	5/6/2018	08:04:21	COM5	151.00	0.00	13.22	Shutdown and washed pumps and lines until clean.
Event	16	Drop Top Plug	Drop Top Plug	5/6/2018	08:13:51	COM5	13.00	0.00	0.26	Dropped the top plug, which was witnessed by the customer.
Event	17	Pump Displacement	Pump Displacement	5/6/2018	08:13:55	COM5	13.00	0.00	0.24	Pumped 326.8 bbls. of fresh water with MMCR in the first 20 bbls. and last 70 bbls. Biocide and Clayweb was added throughout the rest of displacement.
Event	18	Shutdown	Shutdown	5/6/2018	09:02:05	USER	2356.00	0.00	8.18	Lost prime on 4 X 4 centrifugal pump. Shutdown to reprime the 4

Event	ID	Description	Activity	Date	Time	User	Cost	Volume	Pressure	Notes
										X 4 pump.
Event	19	Resume	Resume	5/6/2018	09:05:05	USER	2363.00	0.90	8.18	Resumed the rest of displacement.
Event	20	Bump Plug	Bump Plug	5/6/2018	09:10:08	COM5	3505.00	0.00	8.21	Bumped the plug 500 psi. over 2,900 psi. at 3 bpm. Finale pressure was 3,500 psi. Held pressure for 5 minutes. Pressure held. Circulated 40 bbls. of Tuned III spacer, and 26 bbls. of cement to surface.
Event	21	Pressure Up Well	Pressure Up Well	5/6/2018	09:14:53	COM5	3605.00	0.00	8.21	P
Event	22	Check Floats	Check Floats	5/6/2018	09:16:54	USER	2827.00	4.70	8.17	Bled off pressure to check floats. Floats held. Got 2.5 bbls. of fluid back to the truck.
Event	23	End Job	End Job	5/6/2018	09:19:57	COM5	11.00	0.00	8.10	Washed and blew down all pumps and lines until clean and dry.
Event	24	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	5/6/2018	09:30:00	USER	34.00	1.40	8.15	Halliburton cement crew held a pre rig down safety meeting and JSA.
Event	25	Rig-Down Equipment	Rig-Down Equipment	5/6/2018	09:45:00	USER	28.00	2.10	8.14	Rigged down all lines, hoses and equipment.
Event	26	Depart Location Safety Meeting	Depart Location Safety Meeting	5/6/2018	11:00:00	USER				Held a pre journey safety meeting with the crew.
Event	27	Depart Location for Service Center or Other Site	Depart Location for Service Center or Other Site	5/6/2018	11:15:00	USER				Started journey management with dispatch and left location.

3.0 Attachments

3.1 Harvesters State 4N-16A-M Production.png

