

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401725050

Date Received:

08/06/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed

0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 39560

Name of Operator: TOP OPERATING COMPANY

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Paul Herring

720-663-1698

paul.herring@topoperating.com

OGCC INSPECTION SUMMARY:

FIR Document Number: 690002038

Inspection Date: 07/31/2018

FIR Submit Date: 07/31/2018

FIR Status: _____

Inspected Operator Information:

Company Name: TOP OPERATING COMPANY

Company Number: 39560

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

LOCATION - Location ID: 321291

Location Name: PEDICORD-63N69W Number: 12NESE County: _____

Qtrqr: NESE Sec: 12 Twp: 3N Range: 69W Meridian: 6

Latitude: 40.237025 Longitude: -105.058599

FACILITY - API Number: 05-013- -00 Facility ID: 321291

Facility Name: PEDICORD-63N69W Number: 12NESE

Qtrqr: NESE Sec: 12 Twp: 3N Range: 69W Meridian: 6

Latitude: 40.237025 Longitude: -105.058599

CORRECTIVE ACTIONS:

1 CA# 117762

Corrective Action: Install sign to comply with rule 210.d.

Date: 05/21/2014

Response: CA COMPLETED

Date of Completion: 08/02/2018

Operator
Comment:

The signs were put in place on Thursday, 08/02/2018. Please see attached pictures.

The inspection report states the sign has been missing since 2014. That is incorrect. The sign was placed on the water vault after the 2014 inspection. Weather, vandalism and other factors can affect the longevity of the sign placement. TOP normally inspects for these types of signs. As early as May of this year, the sign was in place. We believe the sign was recently removed.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: The signs were put in place on Thursday, 08/02/2018. Please see attached pictures.

The inspection report states the sign has been missing since 2014. That is incorrect. The sign was placed on the water vault after the 2014 inspection. Weather, vandalism and other factors can affect the longevity of the sign placement. TOP normally inspects for these types of signs. As early as May of this year, the sign was in place. We believe the sign was recently removed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Herring

Signed: _____

Title: Landman

Date: 8/6/2018 10:15:11 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401725063	Picture of signs on water vault
-----------	---------------------------------

Total Attach: 1 Files