

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401728511

Date Received:
08/09/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>
<u>-</u>		<u>SanJuanCOGCC@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602784
Inspection Date: 06/18/2018 FIR Submit Date: 07/03/2018 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333622

Location Name: DEKAY GAS UNIT A-N33N8W Number: 23NWNW County: LA PLATA
Qtrqr: NWN Sec: 23 Twp: 33N Range: 8W Meridian: N
Latitude: 37.094144 Longitude: -107.691901

FACILITY - API Number: 05-067- -00 Facility ID: 215395

Facility Name: DEKAY A Number: 1
Qtrqr: NWN Sec: 23 Twp: 33N Range: 8W Meridian: N
Latitude: 37.094144 Longitude: -107.691901

CORRECTIVE ACTIIONS:

1 CA# 117165

Corrective Action: Stormwater controls are needed to stabilize erosion within the eastern project area. Date: 08/03/2018

Response: CA COMPLETED Date of Completion: 07/24/2018

Operator Comment: Two rock run downs were installed, and a diversion berm installed along the east edge of the well pad to direct water flow to the rock rundowns. The old well sign was removed and disposed of, and the new one secured in place. Trash was removed from the well pad. Five to six thistle plants were hand dug and removed from location. The tank pit sign was confirmed to be present. One rig anchor was confirmed to be marked and the

remaining rig anchors were confirmed to be removed. No stained soils were identified on the well pad.
See attached photos

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Two rock run downs were installed, and a diversion berm installed along the east edge of the well pad to direct water flow to the rock rundowns. The old well sign was removed and disposed of, and the new one secured in place. Trash was removed from the well pad. Five to six thistle plants were hand dug and removed from location. The tank pit sign was confirmed to be present. One rig anchor was confirmed to be marked and the remaining rig anchors were confirmed to be removed. No stained soils were identified on the well pad.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 8/9/2018 7:21:19 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

401728513	Work completion documentation
-----------	-------------------------------

Total Attach: 1 Files