

Status	Receipt	Permit	TWN	tdir	RNG	rdir	SEC	Q160	Q40	UTM_x	UTM_y	Use	Contact/Sample Attempts	Landowner	Landowner Contact
Eliminated - Not Functional	448780	217515	7	N	80	W	18 SW	SE	379990.8	4492205.1	Stock	Visited site on 8/6/18. Spoke with landowner. Well is not functional and no pump is installed. Landowner is not planning on using well in the future.	Michael Telk	970-819-0536	