

On 8/20/2018, COGCC staff inspected the Pinnacle Unit 10-30 as a result of complaint number 200446156. Mr. Stehle with Stehle Oil was on location at the time of inspection. Weather was clear and 75 deg. The well was producing at the time of inspection. Pit had fluid; a slight sheen could be observed around the oil saturated booms, it appeared that the pit has appropriate freeboard, weathered oil could be observed around and in the bank of the pit. At the time of inspection water was being discharged from the pit to the ground and flowing to the pit. Oil staining was observed at the wellhead, not actively leaking. Some small pieces of Trash were observed around the location. The location should be kept free of trash at all times and equipment not necessary for production should be removed. The pit should be operated in a way that prevents the accumulation of oil. Per rule 902, water should be treated prior to discharge in the pit. All visually contaminated soil should be removed and managed per rule 907. See attached photos.



Equipment stored on location. All equipment required for production should be stored in a manner that it does not blow away or become trash. Some trash on the ground; bottle, rope, tube, plastic, etc.



Looking south. Water from tank discharges to the ground to the pit.





Looking west at pit



Booms on pit at pit discharge point. Mr. Stehle said he would remove booms.





Looking west



Discharge to pit.





Back of tanks, looking west.



Back of tanks, looking west.





Front of tank, looking north. Note pit in top left corner of photo.



Looking north





Wellhead, looking west

**STEHLER [REDACTED] PRODUCTION**

PINNACLE UNIT 10/30  
NW SE SEC. 30-3N-86W  
RIO BLANCO COUNTY, COLO.  
FEDERAL LSE. C-23128

IN CASE OF EMERGENCY  
970-824-6909 970-629-1007

08.20.2018 13:40





Behind tank, looking east