

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401744332

Date Received:

08/26/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Timothy Hart</u>	<u>303-999-5420</u>	<u>thart@fremontpetroleum.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 682600536

Inspection Date: 07/19/2018

FIR Submit Date: 07/23/2018

FIR Status: _____

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC

Company Number: 10412

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 451507

Location Name: Bird Number: 13-18 County: FREMONT

Qtrqr: NWS Sec: 18 Twp: 20S Range: 69W Meridian: 6
W

Latitude: 38.306211 Longitude: -105.160133

FACILITY - API Number: 05-043-00 Facility ID: 451506

Facility Name: Bird Number: 13-18

Qtrqr: NWS Sec: 18 Twp: 20S Range: 69W Meridian: 6
W

Latitude: 38.306211 Longitude: -105.160133

CORRECTIVE ACTIIONS:

1 CA# 117591

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 08/24/2018

Response: CA COMPLETED

Date of Completion: 08/17/2018

Operator Comment: Construction crew removed soiled dirt and replaced with clean surrounding dirt.

COGCC Decision: _____

COGCC
Representative:

2 CA# 117592

Corrective Action: Comply with Rule 603.f .

Date: 08/02/2018

Response: CA COMPLETED

Date of Completion: 07/31/2018

Operator
Comment:

Crew removed wooden pallets, lumber pieces, tarp/netting and miscellaneous debris from location.

COGCC Decision:

COGCC
Representative:

3 CA# 117593

Corrective Action: Comply with Rule 1003.a.

Date: 08/24/2018

Response: CA COMPLETED

Date of Completion: 08/17/2018

Operator
Comment:

Crew located all four guy-line anchors and placed markers at each anchor. Markers and anchors were painted with flourescent orange paint to be easily identified on site.

COGCC Decision:

COGCC
Representative:

4 CA# 117594

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: 08/24/2018

Response: CA COMPLETED

Date of Completion: 08/17/2018

Operator
Comment:

Construction crew contoured disturbed area to match natural contouring of surrounding land. Native grass seeds were tilled in and covered with straw mulch to aid in establishment of growth.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator engaged crew and third party construction company to comply with inspection requirements as follows:
1) removed trash and debris from location;
2) removed stained soil where rig had been located and replaced with clean soil;
3) located guy-line anchors and marked with flourescent-orange painted markers;
4) contoured disturbed area to match natural contouring of surrounding land. Reseeded area with approved native grasses and covered with mulch for establishment of growth.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Timothy Hart

Signed:

Title: CEO and President

Date: 8/26/2018 11:17:55 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401744334	photo image
401744335	photo image
401744336	photo image
401744337	photo image
401744338	photo image
401744339	photo image
401744340	photo image
401744341	photo image
401744342	photo image

Total Attach: 9 Files