

## McLin C

Inspection # 689301297



Sediment has been cleared from behind tank battery. The diversion ditch has been re-defined. Erosion control blankets have been installed on the cut slope.



## McLin C



## McLin C



08/16/2018 11:41