

APACHE CANYON 03-11 API# 05-071-09629 – TIMBER CREEK

OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 10, 2018

(3) CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 682600545



APACHE CANYON 03-11 API# 05-071-09629 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 10, 2018  
(3) CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 682600545



Mechanics placed the absorbent pads from the containment pan into a plastic bag and sealed the contents. The contents were transported to the designated container for waste storage. Once the container is full, the contents will be disposed of in accordance with Rule 907.e.

APACHE CANYON 03-11 API# 05-071-09629 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 10, 2018  
(3) CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 682600545



A vacuum truck was dispatched to the location to remove the oil from the containment pan.

APACHE CANYON 03-11 API# 05-071-09629 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 10, 2018  
(3) CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 682600545



The vacuum truck removed the oil from the containment pan and disposed of in compliance with Rule 907.e.



APACHE CANYON 03-11 API# 05-071-09629 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 10, 2018  
(3) CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 682600545



The mechanic discovered that the oil leak was coming from the oil filter.

APACHE CANYON 03-11 API# 05-071-09629 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 10, 2018  
(3) CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 682600545



A new oil filter was installed securely to comply with Rule 605.d.

APACHE CANYON 03-11 API# 05-071-09629 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 10, 2018  
(3) CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 682600545



The absorbent pads and oil accumulation have been removed from the containment below the engine.



APACHE CANYON 03-11 API# 05-071-09629 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 10, 2018  
(3) CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 682600545



The absorbent pads and oil accumulation have been removed from the containment below the engine.



APACHE CANYON 03-11 API# 05-071-09629 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 10, 2018  
(3) CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 682600545



Trash in the production pit.

APACHE CANYON 03-11 API# 05-071-09629 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 10, 2018  
(3) CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 682600545



Trash in the production pit was removed to comply with Rule 603.f.