

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2018

Submitted Date:

09/07/2018

Document Number:

693700008**FIELD INSPECTION FORM**Loc ID 305243 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275909	WELL	PA	03/31/2016	OW	123-22699	WIEDEMAN 20-20	EI
444663	SPILL OR RELEASE	CL	02/01/2016		-	Wiedeman 20-20	EI

General Comment:

Inspected Facilities									
Facility ID:	275909	Type:	WELL	API Number:	123-22699	Status:	PA	Insp. Status:	EI
Facility ID:	444663	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI

Environmental

Spill/Remediation:

Comment: COGCC followup inspection of Remediation #9687. Most recent submittal dted 5/14/2018 for Q12018 monitoring. SVE/AS operating. Monitoring wells appear secure. One monitoring well damaaged (see photo). Continue quarterly reporting for this project.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Rill forming on location and straw waddles on east side becoming silted in. Stormwater control requires maintenance to prevent future sediment transport offsite.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 10/07/2018

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401756819	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573105
693700009	Field Photos 9-5-2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573104