

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401763284

Date Received:

09/14/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Abigail Wenk</u>	<u>303-802-6655</u>	<u>awenk@bisonog.com</u>
<u>Todd Wolff</u>	<u>303-526-6404</u>	<u>twolff@bisonog.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 682503879

Inspection Date: 09/13/2018

FIR Submit Date: 09/13/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 457131

Location Name: Hunt 8-60 Number: 17A County: \_\_\_\_\_

Qtrqr: SWN Sec: 17 Twp: 8N Range: 60W Meridian: 6  
W

Latitude: 40.663456 Longitude: -104.123217

FACILITY - API Number: 05-123- -00 Facility ID: 457131

Facility Name: Hunt 8-60 Number: 17A

Qtrqr: SWN Sec: 17 Twp: 8N Range: 60W Meridian: 6  
W

Latitude: 40.663456 Longitude: -104.123217

CORRECTIVE ACTIONS:

1 CA# 118687

Corrective Action: Provide detailed calculations with documentation showing the topsoil depth on the location, and the amount of topsoil horizon that the operator salvaged, separated and stored for the location in accordance with 1002.b.(2). A corrective action date of two weeks is being provided as soil salvage and pad construction in ongoing.

Date: 09/27/2018

Response: CA COMPLETED

Date of Completion: 09/14/2018

Current calculations show that there is 11,966 cy in the topsoil pile and when we are finished there will be

Operator  
Comment:

approximately 14,000 cy. See attached document for the current calculation detail.

We also plan to lower the entire pad by 5-6", layer 2" of sand, then place clay material over the top and bring back to level grade.

COGCC Decision:

\_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Abigail Wenk

Signed:

\_\_\_\_\_

Title: Regulatory Manager

Date: 9/14/2018 10:01:54 AM

\_\_\_\_\_

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

401763385

Calculation Backup

Total Attach: 1 Files