

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401678813
Date Received:
06/19/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		Sabre.Beebe@bp.com
.		SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602599
Inspection Date: 04/12/2018 FIR Submit Date: 04/23/2018 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333510

Location Name: BONDAD 33-10-N33N10W Number: 2SENE County: LA PLATA
Qtrqtr: SENE Sec: 2 Twp: 33N Range: 10W Meridian: N
Latitude: 37.135642 Longitude: -107.897993

FACILITY - API Number: 05-067- -00 Facility ID: 259310

Facility Name: FRANK DAVIS B Number: 2
Qtrqtr: SENE Sec: 2 Twp: 33N Range: 10W Meridian: N
Latitude: 37.135642 Longitude: -107.897993

CORRECTIVE ACTIONS:

1 ☒ CA# 115999

Corrective Action: Revegetate the western portion of the project area. Date: 05/31/2018

Response: CA COMPLETED Date of Completion: 05/30/2018

Operator Comment: Seeding and mulching performed on bare and disturbed areas see attached photos

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 116000

Corrective Action: Well pad stormwater diversion needs maintenance. Diversion outlet in the southwestern corner needs repair and replacement. Erosional channels and rilling along the access road needs to be stabilized. Stormwater controls along access need maintenance/repair and improvement to de-energize flows and capture sediment.

Date: 05/31/2018

Response: CA COMPLETED

Date of Completion: 05/30/2018

Operator Comment: Storm water BMP's have been maintained in addition to installation of additional measures to control the large volumn of storm water coming off the hill side adjacent to the well pad.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: BP and Logos collaborated on Stormwater and seeding measures installed on this well pad. See attached photos of work completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 6/19/2018 3:50:57 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401678813	FIR RESOLUTION SUBMITTED
401678839	work completion photos

Total Attach: 2 Files