

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401688454  
Date Received:  
06/28/2018

## FIR RESOLUTION FORM

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		Sabre.Beebe@bp.com
.		SanJuanCOGCC@bp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 680602339  
Inspection Date: 12/08/2017 FIR Submit Date: 12/22/2017 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 325978

Location Name: Ray, Billy GU Number: 3 County: LA PLATA  
Qtrqr: SWN Sec: 19 Twp: 34N Range: 9W Meridian: M  
W  
Latitude: 37.179354 Longitude: -107.872341

### FACILITY - API Number: 05-067- -00 Facility ID: 215669

Facility Name: BILLY RAY Number: 1  
Qtrqr: SWN Sec: 19 Twp: 34N Range: 9W Meridian: M  
W  
Latitude: 37.179354 Longitude: -107.872341

### CORRECTIVE ACTIONS:

1 ☒ CA# 113654

Corrective Action: Remove or mow kochia debris in the western portion of the project area. Date: 01/31/2018

Response: CA COMPLETED Date of Completion: 01/04/2018

Operator Comment: Weeds and weed debris has been removed from location and this location has been placed on the priority list for treatment in the 2018 weed management program. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 113655

Corrective Action: Weedy and bare area in the southwestern portion of the project area needs revegetation. Seeding should be initiated within the spring 2018 seeding window. Soil sampling and remediation may be needed for successful vegetation establishment.

Date: 05/01/2018

Response: CA COMPLETED

Date of Completion: 01/04/2018

Operator  
Comment: Seeding of bare areas was performed see attached

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All CA have been addressed see attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 6/28/2018 11:25:36 AM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401688454	FIR RESOLUTION SUBMITTED
401688466	CA photos of completion

Total Attach: 2 Files