

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401689212

Date Received:

06/28/2018

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

SanJuanCOGCC@bp.com

Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602719

Inspection Date: 06/01/2018

FIR Submit Date: 06/01/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326656

Location Name: TILLMAN BURCH GAS UNIT- N33N8W Number: 12SENE County: LA PLATA

Qtrqr: SENE Sec: 12 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122253 Longitude: -107.663255

FACILITY - API Number: 05-067- -00 Facility ID: 261488

Facility Name: TILLMAN BURCH Number: 2

Qtrqr: SENE Sec: 12 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122253 Longitude: -107.663255

CORRECTIVE ACTIONS:

1 ☒ CA# 116625

Corrective Action: Remove debris.

Date: 06/30/2018

Response: CA COMPLETED

Date of Completion: 06/28/2018

Operator
Comment:

Debris and fencing removed and disposed of properly see attached

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 116626

Corrective Action: Thistles will need to be treated this year where rosettes observed. Seeds will remain viable for 10-15 years and therefore, subsequent monitoring and treatment will be needed.

Date: 06/30/2018

Response: CA COMPLETED

Date of Completion: 06/28/2018

Operator
Comment: Weed debris has been removed and disposed of properly and weed contractor has treated rosettes. see attached.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 116627

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area.

Date: 06/30/2018

Response: CA COMPLETED

Date of Completion: 06/28/2018

Operator
Comment: Rock rundowns have been installed in erosion features to prevent future erosion and reduce velocity of storm water. see attached.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All CA addressed see attached

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 6/28/2018 4:05:05 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

401689212	FIR RESOLUTION SUBMITTED
401689227	CA completion photos

Total Attach: 2 Files