



STATE OF
COLORADO

API# 121-05567
LOC# 316960
Doc# 2303010
Date: 10/01/2018

EnviroScan - DNR, OGCC <dnr_ogcc.enviroscan@state.co.us>

Blumenkamp 4 (API 121-05567, Loc ID 316960)

1 message

Deranleau - DNR, Greg <greg.deranleau@state.co.us>

Thu, Sep 20, 2018 at 2:36 PM

To: Randy Ward <randy@wardoil.com>

Cc: Rob Young <rob.young@state.co.us>, Diana Burn <Diana.Burn@state.co.us>

Randy,

Based on our conversation today, it is my understanding that the Blumenkamp 4 well is experiencing similar issues to those occurring at the State 3 (API 121-05603). COGCC will review the Form 4 you have submitted to run in and cement a 4-1/2" liner so that you can get going on that work. Please submit a Form 19 in accordance with Rule 906 to document the spill at the surface as soon as possible; the initial spill report would be due within 72 hours of discovery, and it sounds like this situation has been going on longer than that.

Lastly, when COGCC inspected this well on February 8, 2018, there was an excavation at the wellhead. Can you please describe the work that was going on at the time and the outcome of any investigation or repairs done then. Has additional work been done since then?

Thanks for your cooperation.

Greg

--

Greg Deranleau

Environmental Manager



P 303.894.2100 x5153

1120 Lincoln Street, Suite 801, Denver, CO 80203

greg.deranleau@state.co.us | www.colorado.gov/cogcc

Cc: API 121-05567 & Location ID 316960: "CORRESPONDENCE TO WARD" 9/20/18