

Inspector Name:

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2018

Submitted Date:

09/26/2018

Document Number:

682600556

FIELD INSPECTION FORM

Loc ID 308460 Inspector Name: _____ On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10084

Name of Operator: PIONEER NATURAL RESOURCES USA INC

Address: 5205 N O'CONNOR BLVD STE 200

City: IRVING State: TX Zip: 75039

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections
Inspections, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272396	WELL	PR	09/13/2004	GW	071-08074	NORRIS 44-31	EI

General Comment:

[This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

Inspector Name:

Location

Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:

Type	Area	Volume
------	------	--------

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS			37.209529,-104.705958
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment: Inadequate berms around tank. Berms or other secondary containment devices shall be constructed around crude oil, condensate, and produced water tanks to provide secondary containment for the largest single tank and sufficient freeboard to contain precipitation.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 10/27/2018

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type
Comment:
Corrective Action:
Date:

Inspector Name:

Inspected Facilities

Facility ID: 272396 Type: WELL API Number: 071-08074 Status: PR Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401775189	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4589509
682600557	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4589506