



99999999

OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT☒ NOTICE OF UNSATISFACTORY INSPECTION
☐ NOTICE OF SATISFACTORY INSPECTION1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05-	(121 - 07096)	LEASE NAME:	Redress 2A
LOCATION:	SESW 2-2N-54	OPERATOR:	ENERGY SEARCH
DATE:	3-6-97	INSPECTOR:	EBB
Insp. Type:	ID	Insp. Status:	TA
PA:	Y	N	Pass/Fail: P
		F	Viol.: Y
		N	NOV: Y
			N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	None	(Kenia West Unit)
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)	None. 1 Gas line to this	
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)	site needs to be removed	
General Housekeeping (Rule 603)	or marked for visibility.	
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)	tubing hung in casinghead	
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous	Snak, cement and old oily soil at site.	



00064875

CORRECTIVE ACTION REQUIRED:

Comply with Rule 326, MIT
within 30 days and install well sign, or plug in 6 months.

Date Corrective Action Required By: 9-7-97

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

APR 16 1997