

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401279132
Date Received:
04/16/2018

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 52530

Name of Operator: MAGPIE OPERATING, INC

Address: 2707 SOUTH COUNTY RD 11

City: LOVELAND State: CO Zip: 80537

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Warner, Ryan and James

(970) 669-6308

magpieoil@yahoo.com

Ikenouye, Teri

teri.ikenouye@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 673715324

Inspection Date: 04/24/2017

FIR Submit Date: 04/25/2017

FIR Status: _____

Inspected Operator Information:

Company Name: MAGPIE OPERATING, INC

Company Number: 52530

Address: 2707 SOUTH COUNTY RD 11

City: LOVELAND State: CO Zip: 80537

LOCATION - Location ID: 316982

Location Name: LITTLE BEAVER UNIT-62S56W Number: 5SWNW County: WASHINGTON

Qtrqtr: SWN Sec: 5 Twp: 2S Range: 56W Meridian: 6

Latitude: 39.909231 Longitude: -103.685761

FACILITY - API Number: 05-121-00 Facility ID: 234084

Facility Name: LITTLE BEAVER UNIT Number: 52

Qtrqtr: SWN Sec: 5 Twp: 2S Range: 56W Meridian: 6

Latitude: 39.909231 Longitude: -103.685761

CORRECTIVE ACTIONS:

1 ☒ CA# 71170

Corrective Action: Contacted Operator on 4/24/2017. Pumper is on the way to fix valve. Clean up stained soil.

Date: 05/09/2017

Response: CA COMPLETED

Date of Completion: 08/04/2017

On August 4, 2017, Magpie field superintendent removed the water from the COGCC named culvert and tinhorn pit (approximately 25 gallons total) and disposed of the water in the produced water tank at Little Beaver Unit

Operator Comment: Injection Plant. The 'culvert' and 'tinhorn pit' are in actuality, valve boxes. Liquid did not return into the valve boxes, and the field superintendent stated the liquid in the valve boxes was believed to be rain water that had collected.

COGCC Decision: Approved

COGCC Representative:

2 ☒ CA# 71171

Corrective Action: Remove or remediate stained soil at wellhead.

Date: 05/26/2017

Response: CA COMPLETED

Date of Completion: 08/04/2017

Operator Comment: On August 4, 2017, Magpie field superintendent removed stained soil around the well head and placed on tarp. Soil was picked up at a later date and disposed of with other removed/remediated soil during site assesment activities April 4, 2018.

COGCC Decision: Approved

COGCC Representative:

3 ☒ CA# 71172

Corrective Action: Clean up stained soil at gear box.

Date: 05/09/2017

Response: CA COMPLETED

Date of Completion: 08/04/2017

Operator Comment: On August 4, 2017, Magpie field superintendent removed stained soil around the gear box and placed on tarp. Soil was picked up at a later date and disposed of with other removed/remediated soil during site assesment activities, April 4, 2018.

COGCC Decision: Approved

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Magpie reserves the right to supplement this FIRR with other documentation related to the various inspections, including documentation demonstrating corrective actions have been closed out at an earlier date than noted in this FIRR.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Warner

Signed: _____

Title: Vice President

Date: 4/16/2018 8:32:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401279132	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files