

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401817956

Date Received:

10/31/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Sessions, Tamra

tsessions@logosresourcesllc.com

Rowley, Darren

drowley@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602995

Inspection Date: 08/16/2018

FIR Submit Date: 09/04/2018

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 333627

Location Name: COLORADO 32-7-N32N7W Number: 3SWNE County: LA PLATA

Qtrqtr: SWNE Sec: 3 Twp: 32N Range: 7W Meridian: N

Latitude: 37.049260 Longitude: -107.592280

FACILITY - API Number: 05-067- -00 Facility ID: 213910

Facility Name: COLORADO 32-7 Number: 11

Qtrqtr: SWNE Sec: 3 Twp: 32N Range: 7W Meridian: N

Latitude: 37.049260 Longitude: -107.592280

CORRECTIVE ACTIONS:

1 CA# 118392

Corrective Action: Remove junk and debris and control non-noxious weeds around fired equipment.

Date: 11/01/2018

Response: CA COMPLETED

Date of Completion: 10/31/2018

Operator Comment: LOGOS Operating collaborated with the land owner to remove the land owner's personal property from within the rig anchor pattern at the Colorado 32-7#11. The surface owner has requested that LOGOS stay within the rig anchor pattern, with the exception of the small area utilized for LOGOS's production equipment.

COGCC Decision: _____

COGCC Representative:	
-----------------------	--

2	CA# 118393	<div style="display: flex; justify-content: space-between;"> <div> <p>Corrective Action: Control weeds at the appropriate time but no later than November 1, 2018.</p> <p>Response: CA COMPLETED</p> <p>Operator Comment: LOGOS did not locate any weeds or debris around the fired equipment, but cleared some vegetation surrounding the well head. LOGOS did not locate any Russian knap weed or any other noxious weeds within the area, but will continue to annually spray, or more frequently if necessary, to prevent noxious weed growth in the area.</p> </div> <div> <p>Date: 11/01/2018</p> <p>Date of Completion: 10/31/2018</p> </div> </div> <p>COGCC Decision: _____</p> <p>COGCC Representative: </p>
----------	-------------------	---

3	CA# 118394	<div style="display: flex; justify-content: space-between;"> <div> <p>Corrective Action: Stormwater controls are needed to stabilize erosion within the project area. Successful revegetation will help stabilize bare soils on cut and fill slopes.</p> <p>Response: CA COMPLETED</p> <p>Operator Comment: The stormwater controls have have been addressed by BP in the inspection that was received by BP. The cut slope portion of the pad is under BP's area of responsibility.</p> </div> <div> <p>Date: 10/05/2018</p> <p>Date of Completion: 10/31/2018</p> </div> </div> <p>COGCC Decision: _____</p> <p>COGCC Representative: </p>
----------	-------------------	---

OPERATOR COMMENT AND SUBMITTAL	
Comment:	
<p>I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.</p> <p>Print Name: Larissa Farrell Signed: _____</p> <p>Title: Environmental Technician Date: 10/31/2018 9:07:00 AM</p>	

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401817995	Surface Owner Letter
401817996	Photo
401817998	Photo
401817999	Photo

Total Attach: 4 Files