

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401818037

Date Received:  
10/31/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Sessions, Tamra

tsessions@logosresourcesllc.com

Rowley, Darren

drowley@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680603011

Inspection Date: 08/16/2018

FIR Submit Date: 09/05/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 326438

Location Name: IGNACIO 33-7-N33N7W Number: 34NWNE County: LA PLATA

Qtrqtr: NWNE Sec: 34 Twp: 33N Range: 7W Meridian: N

Latitude: 37.064570 Longitude: -107.592980

FACILITY - API Number: 05-067- -00 Facility ID: 216491

Facility Name: IGNACIO 33-7 Number: 3A

Qtrqtr: NWNE Sec: 34 Twp: 33N Range: 7W Meridian: N

Latitude: 37.064570 Longitude: -107.592980

CORRECTIVE ACTIONS:

1 CA# 118446

Corrective Action: Seeding needs to be conducted by October 31, 2018. Mulching is recommended for successful vegetation establishment.

Date: 10/31/2018

Response: CA COMPLETED

Date of Completion: 10/22/2018

Operator  
Comment:

This is in response to document #680603011 dated 9/5/2018 in regard to the Ignacio 33-7#3A. LOGOS Operating had BMP's installed and hydro seeded the areas of the cut and fill slopes that had sparse vegetation. Please see attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 118447

Corrective Action: Stabilization measures and stormwater BMPs are needed to stabilize erosion on the well pad cut and fill slopes that are not stabilized with perennial vegetation. Successful revegetation will help achieve long term stabiliization.

Date: 10/31/2018

Response: CA COMPLETED

Date of Completion: 10/22/2018

Operator Comment: This is in response to document #680603011 dated 9/5/2018 in regard to the Ignacio 33-7#3A. LOGOS Operating had BMP's installed and hydro seeded the areas of the cut and fill slopes that had sparse vegetation. Please see attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larissa Farrell

Signed: \_\_\_\_\_

Title: Environmental Technician

Date: 10/31/2018 9:22:56 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401818067	Photo
401818068	Photo
401818069	Photo
401818070	Photo
401818072	Photo
401818073	Photo

Total Attach: 6 Files