

FORM  
6Rev  
05/18

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

401402116

Date Received:

09/13/2017

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 31257

Contact Name: Gene Fritzler

Name of Operator: FRITZLER RESOURCES INC

Phone: (970) 867-9388

Address: P O BOX 114

Fax: (866) 437-4804

City: FORT MORGAN State: CO Zip: 80701

Email: gfritzler@bresnan.net

For "Intent" 24 hour notice required,

Name: \_\_\_\_\_ Tel: \_\_\_\_\_

COGCC contact:

Email: \_\_\_\_\_

API Number 05-075-09233-00

Well Name: BLOOD SPRING

Well Number: 1

Location: QtrQtr: SESE Section: 1 Township: 9N Range: 54W Meridian: 6

County: LOGAN

Federal, Indian or State Lease Number: \_\_\_\_\_

Field Name: BLOOD SPRING

Field Number: 6907

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.777044

Longitude: -103.348011

GPS Data:

Date of Measurement: 06/09/2008

PDOP Reading: 1.7

GPS Instrument Operator's Name: Gene Fritzler, PE

Reason for Abandonment:

☐ Dry☐ Production Sub-economic☐ Mechanical Problems☐ Other \_\_\_\_\_Casing to be pulled: ☐ Yes☐ No

Estimated Depth: \_\_\_\_\_

Fish in Hole: ☐ Yes☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:

☐ Yes☐ No

If yes, explain details below

Details: \_\_\_\_\_

## Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	5060	5064	08/10/2015	B PLUG CEMENT TOP	4900

Total: 1 zone(s)

## Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	23	138	85	138	0	VISU
1ST	7+7/8	5+1/2	14	5,150	125	5,150	4,440	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4900 with 3 sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 54 sks cmt from 925 ft. to 825 ft. Plug Type: STUB PLUG Plug Tagged: ☐  
Set 40 sks cmt from 400 ft. to 300 ft. Plug Type: OPEN HOLE Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 73 sacks half in. half out surface casing from 190 ft. to 72 ft. Plug Tagged: ☒

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: 885 ft. 5+1/2 inch casing Plugging Date: 08/16/2015

\*Wireline Contractor: Brand X Wireline, LLC

\*Cementing Contractor: Yetter Well Service, Inc.

Type of Cement and Additives Used: Type 1 & 2 Portland Cement, 14.5 ppg, and 15 ppg w 1/2 sx chlorides

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

\*ATTACH JOB SUMMARY

Technical Detail/Comments:

--

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Gene Fritzler

Title: VP Date: 9/13/2017 Email: gfritzler@bresnan.net

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Bouzek, Jared Date: 11/1/2018

### CONDITIONS OF APPROVAL, IF ANY:

COA Type	Description
----------	-------------

--	--

### Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401402116	FORM 6 SUBSEQUENT SUBMITTED
401402270	CEMENT JOB SUMMARY
401402291	WIRELINER JOB SUMMARY
401402295	OTHER
401402301	WELLBORE DIAGRAM

Total Attach: 5 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Verified as-built GPS data on COGIS. Verified Well Completion Report (Doc# 241482, 6/17/1991) perf interval 5060-5064' J Sand. Form 6 Notice of Intent to Abandon (Doc# 2440347, approved 8/5/2015, expired 2/4/2016). Verified monthly reporting shows PA as of Aug. 2015.  Permitting review complete.	09/14/2017

Total: 1 comment(s)