

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2018

Submitted Date:

11/07/2018

Document Number:

688000204**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Trujillo, Aaron		aaron.trujillo@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	

**General Comment:**Environmental inspection related to recent produced water spill. No eForm 19 Spill Report has been recieved by COGCC as of 11/7/2018.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment:

Former landfarm area corrective action for weed control has been performed.

Corrective Action:

Date:

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 109572Lat: 39.705472Long: -103.366270Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: 

Comment:

Field inspection #682504077 required operator to submit an eForm 19 within 72 hours (11/04/2018) and contact NE EPS. EPS was contacted, no eForm 19 has been received as of 11/07/2018.

Corrective Action

Submit initial eForm 19.

Date: 11/04/2018**Fencing:**Fencing Type: Fencing Condition: Comment: 

Corrective Action

Date: **Netting:**Netting Type: Netting Condition: Comment: 

Corrective Action

Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: 

Corrective Action

Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000205	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4637409">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4637409</a>