


Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Nov 8, 2018 10:06:30
37.033474N 102.215841W

Wellhead lease sign

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Wellhead lease sign

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Tank battery lease sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Nov 8, 2018 10:07:47
37.033357N 102.215947W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Nov 8, 2018 10:08:21
37.033388N 102.215843W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Nov 8, 2018 10:10:02
37.033697N 102.215757W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Nov 8, 2018 10:09:50
37.033652N 102.215795W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Evidence of tank overflowing and stained soil in containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Produced water tank has overflowed in the past.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Nov 8, 2018 10:11:00
37 033826N 102.215786W

Inadequate berm around tank battery. Stained soil in containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Inadequate berms around tank battery and heater treater.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Nov 8, 2018 10:13:37
37.033690N 102.215880W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Nov 8, 2018 10:12:22
37.033796N 102.215735W

Crude oil tanks have overflowed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Nov 8, 2018 10:12:31
37.033806N 102.215690W

Crude oil tanks have overflowed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Reportable spill from heater treater inside containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Nov 8, 2018 10:14:08
37.033693N 102.216040W

Spill around heater treater



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Holt 1 433758 Inspection Date: 11/9/2018



Roustabout crew on location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources