

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401772486  
Date Received:  
09/24/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10409  
Name of Operator: PEAKVIEW OPERATING COMPANY LLC  
Address: 707 SEVENTEENTH ST STE 4200  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Walters, Steve	720-402-3081	swalters@peakviewenergy.com
Wise, Wayne	720-402-3085	wwise@peakviewenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689801299  
Inspection Date: 06/25/2018 FIR Submit Date: 06/26/2018 FIR Status:

Inspected Operator Information:

Company Name: PEAKVIEW OPERATING COMPANY LLC Company Number: 10409  
Address: 707 SEVENTEENTH ST STE 4200  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 316759

Location Name: GRASSY CREEK COAL CO-66N87W Number: 26SWNW County: ROUTT  
Qtrqtr: SWN Sec: 26 Twp: 6N Range: 87W Meridian: 6  
Latitude: 40.449694 Longitude: -107.121523

FACILITY - API Number: 05-107-00 Facility ID: 232664

Facility Name: GRASSY CREEK COAL CO Number: 3  
Qtrqtr: SWN Sec: 26 Twp: 6N Range: 87W Meridian: 6  
Latitude: 40.449694 Longitude: -107.121523

CORRECTIVE ACTIIONS:

1 CA# 117013

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 07/26/2018

Response: CA COMPLETED

Date of Completion: 07/28/2018

Operator Comment: Stained soil around the wellhead and on the side of the pumping unit was removed and remediated. Stained soil was a result of recent well work. Cleanup work started Monday July 23rd and finished Saturday July 28th. Wellhead was washed down and clean gravel placed in areas where the stained soil had been removed. In the future, mitigation efforts will include using oil absorbent pads during well work operations.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Whenever well servicing operations are conducted, oil pads will be placed around the wellhead and along side of the pumping unit.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Wayne Wise

Signed: \_\_\_\_\_

Title: Operations Engineer

Date: 9/24/2018 1:00:37 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

401772486	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files