

**Federal MV-7-4**  
**Api # 05-045-06614**  
**Inspection # 689702068**



**Sign is discolored.**

**Federal MV-7-4**  
**Api # 05-045-06614**  
**Inspection # 689702068**



**Unused/unneeded equipment/materials.**



**Federal MV-7-4  
Api # 05-045-06614  
Inspection # 689702068**



**Unused/unneeded equipment/materials.**





**Unused/unneeded equipment/materials.**



**Federal MV-7-4**  
**Api # 05-045-06614**  
**Inspection # 689702068**



**Unmarked deadman.**



**Federal MV-7-4**  
**Api # 05-045-06614**  
**Inspection # 689702068**



**Undersized deadman marker.**



**Deadman maker knocked over and broken.**

**Federal MV-7-4**  
**Api # 05-045-06614**  
**Inspection # 689702068**



**Capacity is faded.**



**Capacity is faded.**



**Federal MV-7-4**  
**Api # 05-045-06614**  
**Inspection # 689702068**



**BMP's damaged and unmaintained.**



**BMP's damaged and unmaintained.**



**Federal MV-7-4**  
**Api # 05-045-06614**  
**Inspection # 689702068**



**Weeds around heated separators.**



**Federal MV-7-4**  
**Api # 05-045-06614**  
**Inspection # 689702068**



**Dead weeds at well heads.**