

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



The phone number for local emergency services (911 where available) is not posted on battery sign.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Pump jack with fenced separator behind.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Tank battery facility

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Tank battery facility

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Stained ground surface around separator by pump jack.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Stained ground surface around compressor.



Stained ground surface around compressor.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Stained ground surface around compressor.



Stained ground surface around compressor.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Stained ground surface inside of tank battery berm.



Stained ground surface inside of tank battery berm.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Unused equipment.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Unlabeled containers.



Unlabeled containers.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Unlabeled container.



Unlabeled container.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Tank not correctly labeled.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Barrel of condensate at compressor with out secondary containment.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Sheet metal debris



Sheet metal debris and dead weeds outside of tank battery fence.

TEXACO FEE 6217
Api # 05-045-07220
Inspection # 689702074



Hole in tank berm liner.