


<b>FORM</b> <b>6</b> <small>Rev 05/18</small>	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> <small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small>				<table border="1" style="width:100%; border-collapse: collapse;"><tr><td style="width:12.5%;">DE</td><td style="width:12.5%;">ET</td><td style="width:12.5%;">OE</td><td style="width:12.5%;">ES</td></tr></table>				DE	ET	OE	ES															
	DE	ET	OE	ES																							
	<b>WELL ABANDONMENT REPORT</b>				<b>Replug By Other Operator</b>																						
<p>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.</p> <p>A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</p>				<p>Document Number:  401795293</p> <p>Date Received:  10/13/2018</p>																							
<b>OGCC Operator Number:</b> 10661					<b>Contact Name:</b> Elizabeth Kane																						
<b>Name of Operator:</b> BISON OIL & GAS II LLC					<b>Phone:</b> (720) 644-6997																						
<b>Address:</b> 518 17TH STREET #1800					<b>Fax:</b>																						
<b>City:</b> DENVER <b>State:</b> CO <b>Zip:</b> 80202					<b>Email:</b> ekane@bisonog.com																						
<b>For "Intent" 24 hour notice required,</b>					<b>Name:</b> Evins, Bret <b>Tel:</b> (970) 420-6699																						
<b>COGCC contact:</b>					<b>Email:</b> bret.evins@state.co.us																						
<b>API Number</b> 05-123-05578-00					<b>Well Number:</b> 1																						
<b>Well Name:</b> DUELL																											
<b>Location:</b> QtrQtr: NWSE      Section: 11      Township: 8N      Range: 61W      Meridian: 6																											
<b>County:</b> WELD					<b>Federal, Indian or State Lease Number:</b>																						
<b>Field Name:</b> WILDCAT					<b>Field Number:</b> 99999																						
<input checked="" type="checkbox"/> <b>Notice of Intent to Abandon</b>					<input type="checkbox"/> <b>Subsequent Report of Abandonment</b>																						
<i>Only Complete the Following Background Information for Intent to Abandon</i>																											
<b>Latitude:</b> 40.674827					<b>Longitude:</b> -104.169732																						
<b>GPS Data:</b>																											
<b>Date of Measurement:</b> 08/28/2018					<b>PDOP Reading:</b> 2.2		<b>GPS Instrument Operator's Name:</b> James Freshwater																				
<b>Reason for Abandonment:</b> <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems																											
<input checked="" type="checkbox"/> <b>Other</b> Re-enter to Re-plug																											
<b>Casing to be pulled:</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					<b>Estimated Depth:</b>																						
<b>Fish in Hole:</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					<b>If yes, explain details below</b>																						
<b>Wellbore has Uncemented Casing leaks:</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					<b>If yes, explain details below</b>																						
<b>Details:</b> <div style="border: 1px solid black; height: 20px; width: 100%;"></div>																											
<b>Current and Previously Abandoned Zones</b>																											
<table border="1" style="width:100%; border-collapse: collapse;"><thead><tr><th style="width:25%;">Formation</th><th style="width:10%;">Perf. Top</th><th style="width:10%;">Perf. Btm</th><th style="width:20%;">Abandoned Date</th><th style="width:20%;">Method of Isolation</th><th style="width:15%;">Plug Depth</th></tr></thead><tbody><tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr></tbody></table>										Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth												
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																						
Total: 0 zone(s)																											
<b>Casing History</b>																											
<table border="1" style="width:100%; border-collapse: collapse;"><thead><tr><th style="width:12.5%;">Casing Type</th><th style="width:10%;">Size of Hole</th><th style="width:10%;">Size of Casing</th><th style="width:10%;">Weight Per Foot</th><th style="width:10%;">Setting Depth</th><th style="width:10%;">Sacks Cement</th><th style="width:10%;">Cement Bot</th><th style="width:10%;">Cement Top</th><th style="width:10%;">Status</th></tr></thead><tbody><tr><td>SURF</td><td>16</td><td>10+3/4</td><td>32.75</td><td>379</td><td>300</td><td>379</td><td>0</td><td> </td></tr></tbody></table>										Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status	SURF	16	10+3/4	32.75	379	300	379	0	
Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status																			
SURF	16	10+3/4	32.75	379	300	379	0																				

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 50 sks cmt from 6709 ft. to 6559 ft. Plug Type: OPEN HOLE Plug Tagged: ☐  
Set 99 sks cmt from 6459 ft. to 6159 ft. Plug Type: OPEN HOLE Plug Tagged: ☒  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 317 sacks half in. half out surface casing from 641 ft. to 0 ft. Plug Tagged: ☒

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_  
of \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

Purpose is to re-enter and adequately re-plug prior to hydraulic stimulation of proposed horizontal well per DJ Basin Offset Policy, dated December 16, 2013.

Closed loop system will be used.

See attached Operations Summary for Re-entry and Re-plugging procedures.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Abigail Wenk

Title: Regulatory Manager Date: 10/13/2018 Email: awenk@bisonog.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 11/16/2018

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_

Expiration Date: 5/15/2019

<b>COA Type</b>	<b>Description</b>
	1) Provide 48 hour notice of MIRU via electronic Form 42. 2) Niobrara plug: There must be 100' of cement above Niobrara. Tag plug 100' above top of Niobrara. 3) Shoe plug: Tag plug 50' above surface casing shoe, if not circulated to surface as proposed, and cement from 50' to surface.

### **Attachment Check List**

<b>Att Doc Num</b>	<b>Name</b>
401795293	FORM 6 INTENT SUBMITTED
401795294	WELLBORE DIAGRAM
401795295	LOCATION PHOTO
401795296	OPERATIONS SUMMARY
401795297	WELLBORE DIAGRAM
401795298	SURFACE OWNER CONSENT

Total Attach: 6 Files

### **General Comments**

<b>User Group</b>	<b>Comment</b>	<b>Comment Date</b>
Well File Verification	Pass	10/18/2018
Permit	Pass	10/17/2018

Total: 2 comment(s)