

Environmental

Spills/Releases:

Type of Spill: CONDENSATE

Estimated Spill Volume: 3

Comment: Insp to assess impact of spill# 458838, 2-3 bbl condensate spill from separator. 25F, sunny w no wind at time on inspection. Separator has been removed and soil excavated to ~14'x20'x5'deep. No petroluem staining or odor observed in excavation. Spoils appear to have been removed and remaining soil stockpile appears to be clean overburden and/or import with no stain or odor.

Corrective Action: Per F-19 COA: Assess nature and extent of contamination with confirmation soil samples. Remediate to Table 910-1 standards and provide documentation in a either a Supplemental F-19 if cleaned up immediately and/or F-27 if extended remediation such as landfarming contaminated soil is required. Landfarming must also be approved by surface owner. Documentation must include a figure showing spill area with sample locations plus laboratory results.

Date: 12/20/2018

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401846338	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4650970
690300383	Insp photos 11-9-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4650969