

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401725050

Date Received:

08/06/2018

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 39560

Name of Operator: TOP OPERATING COMPANY

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Paul Herring

720-663-1698

paul.herring@topoperating.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 690002038

Inspection Date: 07/31/2018

FIR Submit Date: 07/31/2018

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TOP OPERATING COMPANY

Company Number: 39560

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

### LOCATION - Location ID: 321291

Location Name: PEDICORD-63N69W Number: 12NESE County: \_\_\_\_\_

Qtrqr: NESE Sec: 12 Twp: 3N Range: 69W Meridian: 6

Latitude: 40.237025 Longitude: -105.058599

### FACILITY - API Number: 05-013- -00 Facility ID: 321291

Facility Name: PEDICORD-63N69W Number: 12NESE

Qtrqr: NESE Sec: 12 Twp: 3N Range: 69W Meridian: 6

Latitude: 40.237025 Longitude: -105.058599

### CORRECTIVE ACTIONS:

1 ☒ CA# 117762

Corrective Action: Install sign to comply with rule 210.d.

Date: 05/21/2014

Response: CA COMPLETED

Date of Completion: 08/02/2018

Operator  
Comment:

The signs were put in place on Thursday, 08/02/2018. Please see attached pictures.

The inspection report states the sign has been missing since 2014. That is incorrect. The sign was placed on the water vault after the 2014 inspection. Weather, vandalism and other factors can affect the longevity of the sign placement. TOP normally inspects for these types of signs. As early as May of this year, the sign was in place. We believe the sign was recently removed.

COGCC Decision: Approved

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: The signs were put in place on Thursday, 08/02/2018. Please see attached pictures.

The inspection report states the sign has been missing since 2014. That is incorrect. The sign was placed on the water vault after the 2014 inspection. Weather, vandalism and other factors can affect the longevity of the sign placement. TOP normally inspects for these types of signs. As early as May of this year, the sign was in place. We believe the sign was recently removed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Herring

Signed: \_\_\_\_\_

Title: Landman

Date: 8/6/2018 10:15:11 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

401725050	FIR RESOLUTION SUBMITTED
401725063	Picture of signs on water vault

Total Attach: 2 Files