

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/20/2018

Submitted Date:

12/20/2018

Document Number:

674301256**FIELD INSPECTION FORM**Loc ID 422731 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	
Adamczyk, Megan		megan.adamczyk@state.co.u s	
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422731	LOCATION	AC			-	Frederiksen 63N-68W 1A- 28H	AO

**General Comment:**

**Inspected Facilities**Facility ID: 422731 Type: LOCATION API Number: - Status: AC Insp. Status: AO**Producing Well**Comment: PR

Corrective Action:

Date:

**Complaint**Comment: Inspection in response to complaint. Form 18- #200446804Field Inspector Assigned: Tom PetersonComplaint Received:Date: 12/13/2018Complaint Contacted: AnonymousDate:Location #: 422731Inspection Document #: 674301356Nature of complaint: NoiseField Inspector Actions:On 12/19/2018; I received a complaint in regard to noise on the Fredriksen 1B 28H H368 location, owned and operated by Crestone Peak Resources.On 12/20/2018, I performed a site inspection, I found a recently installed hydraulic pumping unit powered by a natural gas engine.A sound study was conducted in accordance with Rule 802c.Results show average DB @ 52.9. COGCC noise survey results indicate noise levels exceed limits in Rule 802.See inspection document for corrective action detail.All information reviewed and site inspection information were submitted to the complaint specialist for further review.Corrective Action: Comply with Rule 802. Identify and install control measures.Date: 12/21/2018**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674301257	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4683873">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4683873</a>
674301258	Sound survey	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4683874">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4683874</a>