

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/26/2018

Submitted Date:

01/03/2019

Document Number:

682600595

**FIELD INSPECTION FORM**

Loc ID 321959 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 59925  
Name of Operator: MONUMENT GAS MARKETING INC  
Address: P O BOX 950  
City: MONUMENT State: CO Zip: 80132-

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Campbell, Randy	(719) 660-0069	rcampbell0614@comcast.net	President

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285920	WELL	PR	01/31/2007	GW	017-07641	GLADYS COTRELL TRUST 2	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.  
Inadequate berms around tank battery. See corrective action.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: <span style="color: blue;">Inadequate berms around tanks. See attached photos. Berm has a low spot rendering berms ineffective in event of spill.</span>				
Corrective Action: <span style="color: red;">Repair or install berms or other secondary containment devices per Rule 605.a.(4).</span>				
Date: <u>02/04/2019</u>				

**Venting:**

Yes/No	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	Date:

**Flaring:**

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 285920 Type: WELL API Number: 017-07641 Status: PR Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600598	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4693635">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4693635</a>