

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401877652

Date Received:

01/07/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 34725

Name of Operator: GOSNEY & SONS INC

Address: P O BOX 367

City: BAYFIELD State: CO Zip: 81122

Contact Name and Telephone:

Name:

Phone: ( ) Fax: ( )

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Fischer, Alex		alex.fischer@state.co.us
Barnett, Matt		mattb@gosneyco.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800383

Inspection Date: 12/05/2018

FIR Submit Date: 12/07/2018

FIR Status:

Inspected Operator Information:

Company Name: GOSNEY & SONS INC

Company Number: 34725

Address: P O BOX 367

City: BAYFIELD State: CO Zip: 81122

LOCATION - Location ID: 424701

Location Name: KELSALL 33-7 Number: 4-1 County: LA PLATA

Qtrqtr: NENW Sec: 4 Twp: 33N Range: 7W Meridian: N

Latitude: 37.137130 Longitude: -107.614310

FACILITY - API Number: 05-067-00 Facility ID: 424697

Facility Name: KELSALL 33-7 Number: 4-1

Qtrqtr: NENW Sec: 4 Twp: 33N Range: 7W Meridian: N

Latitude: 37.137130 Longitude: -107.614310

CORRECTIVE ACTIONS:

1 CA# 120834

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 01/07/2019

Response: CA COMPLETED

Date of Completion: 01/04/2019

Operator Comment: The lube oil leak underneath the prime mover on the #4-3 pump has been cleaned up. The stained gravel has been placed in temporary containment and will be hauled to landfill when containment approaches capacity.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 120835

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 01/07/2019

Response: CA COMPLETED

Date of Completion: 12/28/2018

Operator Comment: Stained gravel around base of #4-1 and #4-2 wellheads has been removed and placed in temporary containment on location. It will be removed to landfill when containment approaches capacity. Well is prone to minor leakage of produced water with coal fines from time to time. We will mix absorbent material with gravel at base of wellhead (inside cellar) and remove and replace material periodically.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 120836

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 01/07/2019

Response: CA COMPLETED

Date of Completion: 12/28/2018

Operator Comment: The stained gravel caused by the prime mover exhaust has been removed and stored in temporary containment on location. It will be removed to landfill when containment approaches capacity. Well is prone to minor leakage of produced water with coal fines from time to time. We will mix absorbent material with gravel at base of wellhead (inside cellar) and remove and replace material periodically.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**4** CA# 120837

Corrective Action: Comply with Rule 603.f.

Date: 01/07/2019

Response: CA COMPLETED

Date of Completion: 12/17/2018

Operator Comment: The chemical containers, pipes and fittings that were located on the pumpjack base have been moved to offsite inventory storage.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matthew Barnett

Signed: \_\_\_\_\_

Title: General Mgr

Date: 1/7/2019 10:10:28 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files