

KNIGHT W-6-4
Api # 05-045-06506
Inspection # 689702395



KNIGHT GV 51-4

Weeds and brush around location, well and equipment

KNIGHT W-6-4
Api # 05-045-06506
Inspection # 689702395



KNIGHT GV 51-4

Weeds and brush around location, well and equipment

KNIGHT W-6-4
Api # 05-045-06506
Inspection # 689702395



Weeds and brush around location, well and equipment

KNIGHT W-6-4
Api # 05-045-06506
Inspection # 689702395



Unmarked deadman at gas meter and separator.
Weeds and brush around location, well and equipment

KNIGHT W-6-4
Api # 05-045-06506
Inspection # 689702395



KNIGHT W-6-4

Weeds and brush around location, well and equipment

KNIGHT W-6-4
Api # 05-045-06506
Inspection # 689702395



KNIGHT W-6-4

Weeds and brush around location, well and equipment