

Texaco Fee 6217
Api # 05-045-06792
Inspection # 689702415



Contact number added to battery sign.

Texaco Fee 6217
Api # 05-045-06792
Inspection # 689702415



Kicked out snow to check ground surface. No staining noticed.

Texaco Fee 6217
Api # 05-045-06792
Inspection # 689702415



Weeds and debris cleaned up

Texaco Fee 6217
Api # 05-045-06792
Inspection # 689702415



Tank and containers have been removed.

Texaco Fee 6217
Api # 05-045-06792
Inspection # 689702415



Unused equipment has been removed.

Texaco Fee 6217
Api # 05-045-06792
Inspection # 689702415



Compressor shack has been put back together.

Texaco Fee 6217
Api # 05-045-06792
Inspection # 689702415



Stained ground has been cleaned up.

Texaco Fee 6217
Api # 05-045-06792
Inspection # 689702415



Debris removed.