

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Location sign		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	Packing on WH leaking at time of inspection.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 01/17/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 295027 Type: WELL API Number: 071-09533 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Contacted Timber Creek rep about leaking packing. Timber Creek informed me they would send someone out.	silverr	01/16/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401908025	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4706178
688401041	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4706160