

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2019

Submitted Date:

01/18/2019

Document Number:

695100050**FIELD INSPECTION FORM**

Loc ID 307339 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:                     

**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergy.us	<a href="#">All Inspections</a>
Ash, Margaret		margaret.ash@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us	<a href="#">All Inspections</a>
Kosola, Jason		jason.kosola@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217491	WELL	PR	03/13/1997	GW	071-06268	APACHE CANYON 3-5	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	STAINED SOIL INSIDE SOUND WALL AROUND COMPRESSOR. STAINED SOIL ON WEST SIDE OF COMPRESSOR SOIL UNDER COMPRESSOR SKID APPEARS TO BE STAINED AS FAR AS SOIL CAN BE SEEN.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.		Date: 02/19/2019
Type	OTHER		
Comment:	PACKING ON TBG HEAD IS LEAKING		
Corrective Action:	Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.		Date: 02/17/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 217491 Type: WELL API Number: 071-06268 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Comment: PLUMBED TO SURFACECorrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401911101	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4708013">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4708013</a>
695100051	LOC PICS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4708004">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4708004</a>