

Inspection Photos

2/04/2019

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 327492

Inspection Doc. Number: 682504488
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327492



Photo 1: Photo taken from the north end of the location. Photos 1-3 provide an overview of the location from east, to south, to west. Previous inspections documented that compaction alleviation had not been conducted in accordance to reclamation requirements, and required operator to conduct reclamation in accordance to 1004. Photos show reclamation does not appear to have been conducted in accordance with 1000 reclamation requirements; 1004.a requires compaction alleviation to be conducted by cross-ripping to a depth of 18 inches. Location has not been cross-ripped.



Photo 2: See comments under photo 1.



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the location, facing south. Photo shows location appears to have been ripped in one direction. 1004.a requires compaction alleviation to be conducted by cross-ripping to a depth of 18 inches. Location has not been cross-ripped.



Photo 5: Photo taken from the access road, north of the location, facing south. Photo shows access road. Unable to find evidence that compaction alleviation has been conducted in accordance with 1004.a

Inspection Photos

Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327492



Photo 6: Photo taken from the access road, facing south. Previous inspection documented erosion degradation on road and required operator to repair erosion and conduct reclamation in accordance with 1004.a. No additional reclamation activities appear to have been conducted; Access road also does not appear to have been re-contoured or re-graded and erosion degradation remains.