

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401925270

Date Received:

01/31/2019

## FIR RESOLUTION FORM

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 24320

Name of Operator: DIAMOND OPERATING, INC.

Address: 6666 GUNPARK DR STE #200

City: BOULDER State: CO Zip: 80301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Dave Peterson

303-494-4420

davep@flatironenergy.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 688303461

Inspection Date: 01/02/2019

FIR Submit Date: 01/13/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: DIAMOND OPERATING, INC.

Company Number: 24320

Address: 6666 GUNPARK DR STE #200

City: BOULDER State: CO Zip: 80301

### LOCATION - Location ID: 317274

Location Name: IDEA-62S53W Number: 20SENE County: WASHINGTON

Qtrqtr: SENE Sec: 20 Twp: 2S Range: 53W Meridian: 6

Latitude: 39.864470 Longitude: -103.331540

### FACILITY - API Number: 05-121-

-00

Facility ID: 237656

Facility Name: IDEA Number: 1

Qtrqtr: SENE Sec: 20 Twp: 2S Range: 53W Meridian: 6

Latitude: 39.864470 Longitude: -103.331540

### CORRECTIVE ACTIONS:

1 ☒ CA# 121674

Corrective Action: Remove free fluids and contact COGCC EPS staff per Rule 906.b.

Date: 01/15/2019

Response: CA COMPLETED

Date of Completion: 01/18/2019

Operator Comment: Due to the cold weather, the stuffing box rubbers at the wellhead had leaked. This allowed caused on pumping unit which had caused produced fluid to leak at the wellhead. The pumper replaced the stuffing box rubbers to prevent further leaking and picked up a small free oil accumulation. Pumper notified COGCC Inspector, Susan Sherman, upon job completion.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 121675

Corrective Action: Remove free fluids and contact COGCC EPS staff per Rule 906.b.

Date: 01/15/2019

Response: CA COMPLETED

Date of Completion: 01/18/2019

Operator  
Comment:

Removed oil stained soil inside containment berm at the wellhead and disposed of it.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions listed on Field Inspection Form have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dave Peterson

Signed:

Title: President

Date: 1/31/2019 2:23:27 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401925270	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files