

MV 12-3
Api # 045-06522
Inspection # 689702584



Fencing down around wells.

MV 12-3
Api # 045-06522
Inspection # 689702584



Unmarked deadman. Fencing down around wells.

MV 12-3
Api # 045-06522
Inspection # 689702584



Unmarked deadman.

MV 12-3
Api # 045-06522
Inspection # 689702584



Out of service dehydrator.

MV 12-3
Api # 045-06522
Inspection # 689702584



Unused equipment.